



## Gabeldichtsätze ab 1949

Komplette Dichtsätze für Teleskop-Gabeln an Big Twins und Sportstern®. Mit allen Dichtungen um eine Gabel neu abzudichten.

<b>MM3502A</b>	<b>35mm</b>	<b>FX, XL 1971-1972</b>
<b>MM3502B</b>	<b>35mm Kayaba</b>	<b>FX 1973-1977, XL 1973-1974</b>
<b>MM3502C</b>	<b>35mm Showa</b>	<b>FX 1976-1984, FXR 1982-1983, XL 1975-1983</b>
<b>MM3502D</b>	<b>35mm</b>	<b>FX, FXR, XL 1984-1987, nicht für FXRS, FXLR 1987</b>
<b>MM4605A</b>	<b>39mm</b>	<b>XL 1988-2017 (ausser 1200X 2016-2017, 1200CX 2017) Dyna® FXD 1991-2005 ( ausser FXDWG ) FXR 1988-1994, FXRS, FXLR 1987</b>
<b>MM3503A</b>	<b>41mm</b>	<b>FL, FLH 1949-e1977, Servicar GE 1958-1973, Panhead, Shovelhead</b>
<b>MM3503B</b>	<b>41mm</b>	<b>FL L1977-1984, FLT 1980-1983, FXWG 1980-1983, Shovelhead</b>
<b>MM4608E</b>	<b>41mm</b>	<b>Softail® 1984-2017 ( ausser FXSB 2013-2017 ), FXWG 1984-1986, FXDWG 1993-2005, FLD 2012-2016, Touring® 1984-2013</b>
<b>MM4605B</b>	<b>49mm</b>	<b>Dyna® 2006-2017 (ausser FLD 2012-2016), FXCW/C Rocker 2008-2011, FXSB 2013-2017, Touring® 2014-2016, XL 1200X/C 2016-2017, V-Rod® 2002-2011 (ausser Up-Side-Down Gabel)</b>

## Motor-Dichtsätze

Jeweils komplett für einen Motor:

<b>50-30</b>	<b>1930-1936</b>	<b>VL 74ci, VLH 80ci, Flathead Big Twin</b>
<b>50-36G</b>	<b>1937-1948</b>	<b>UL 74ci, ULH 80ci, ers. OEM 17027-36, mit Kupfer-Kopfdichtung, Flathead Big twin</b>
<b>53-40J</b>	<b>1940-1973</b>	<b>WL 40-52, GE Servicar 40-73, 750cc, Kupfer-Kopfdichtung, ers. OEM 17026-40, Flathead</b>
<b>51-36J</b>	<b>1936-1947</b>	<b>EL 61ci, FL 74ci Knucklehead, ers. OEM 17028-36</b>
<b>51-48J</b>	<b>1948-1965</b>	<b>EL 61ci, FL 74ci Panhead, ers. OEM 17028-48</b>
<b>51-66J</b>	<b>1966-1984</b>	<b>FL 66-84, FX 71-84 Shovelhead, Early Shovelhead, ers. OEM 17029-66A, 17029-79</b>
<b>51-84A</b>	<b>1984-1991</b>	<b>Evolution® Big Twin 1340cc 1984-1991, ers. OEM 17035-83A, 17035-89</b>
<b>51-92J</b>	<b>1992-1999</b>	<b>Evolution® Big Twin 1340cc 1992-1999, ers. OEM 17041-92</b>
<b>51-99J</b>	<b>1999-2004</b>	<b>Twin Cam® 88ci Big Twin 99-04, ers. OEM 17053-99</b>
<b>51-05J</b>	<b>2005-2010</b>	<b>Twin Cam® 88ci / 96ci Big Twin 05-10, ers. OEM 17053-05</b>
<b>53-52</b>	<b>1952-1956</b>	<b>K Modell 1952-53, KH Modell 1954-1956, ers. OEM 17026-52</b>
<b>53-57A</b>	<b>1957-1971</b>	<b>Sportster® XL 900cc 1957-71, ers. OEM 17026-57, 17026-71</b>
<b>53-72</b>	<b>1972-e1973</b>	<b>Sportster® XL 1000cc 72-e73, ers. OEM 17026-72</b>
<b>53-72M1</b>	<b>ab 1972-</b>	<b>Sportster® XR 750</b>
<b>53-73J</b>	<b>L1973-1985</b>	<b>Sportster® XL 1000cc L74-85, ers. OEM 17026-73</b>
<b>53-83M1</b>	<b>1983-1984</b>	<b>Sportster® XR 1000</b>
<b>53-86A</b>	<b>1986-1990</b>	<b>Sportster® 883cc / 1200cc, 4-Gang, ers. OEM 17026-86</b>
<b>53-91J</b>	<b>1991-2003</b>	<b>Sportster® 883cc / 1200cc, 5-Gang, ers. OEM 17026-91</b>
<b>53-04J</b>	<b>2004-2006</b>	<b>Sportster® XL 883cc / 1200cc, 2004-2006, ers. OEM 17047-04</b>
<b>53-07J</b>	<b>2007-2017</b>	<b>Sportster® XL 883cc / 1200cc 07-17, ers. OEM 17047-07</b>
<b>53-08J</b>	<b>2008-2012</b>	<b>Sportster® XR 1200, ers. OEM 17027-08</b>